



## Discrepancy Report

Ticket ID : 08045-201-005-00

Contract: CON-ED

Transmit Date: 2015-08-04

## ENVIRONMENTAL FIELD SERVICE

2 KNOLL LN MARLTON NJ 08053

Tel: 609-265-1202

Fax:

Caller: JANINE PRUMACHUK

Email: EFSMAIL@EFSPROBE.COM

---

We are reporting a discrepancy regarding your dig request to locate facilities in the area specified on:

**Ticket ID** : 08045-201-005-00

**Street** : KISCO AVE

**City** : MOUNT KISCO /V

**State** : NY

**Work Start Date** : 08/07/2015 07:00:00

---

The discrepancy information is:

**Discrepancy Type** : 1- \*\*3rd party Unverifiable\*\*\_Plumbing, ECS,  
Cablevision,DEP,DPW etc.

**Facility Type** : Gas & Electric

**Plate #** : 103 cd

**Critical Facility** : No

**Facility Painted** : No

**Rep Notified by Email** : Yes

**Customer / Private Marked** : No

**Type of Customer / Private** :

**Additional notes** : unverifiable can't find work location. contractor must call in  
ticket with a correct address, or location of work place.

Customer Owned Gas Or Electric lines may exist in the work area - it is advised that you use extreme caution when excavating near them. Con Edison does not maintain detailed information on Customer Owned Gas & Electric lines, therefore the accuracy of their markings cannot be guaranteed. To insure a safe excavation, we recommend using a private locate company to locate Customer Owned Utilities.  
Thank You